

Mute BVRD2M Fault Buzzer

Product Range:	VIGIL2
Product Code (if applicable):	BVRD2M
Description of activity:	How to mute BVRD2M (EVAS) fault buzzer via the front panel.
Description of likely fault(s):	NOTE: system fault warning buzzers should NOT be muted unless another means of system fault announcement exists.

IMPORTANT - this product forms part of a life-safety system

Please Note: Periodic inspection and servicing needs to be carried out by a competent person with specialist knowledge of VASs, relevant current training and experience, and with adequate access to spares and sufficient information regarding the system. (BS5839-8).

Description of rectification works:

1. Turn EVAS key to the right
2. Use the arrow keys to move the cursor across to Configure.
3. Press the select button.
4. Use the arrow keys to move the cursor across to text.
5. Use the arrow keys to move the cursor to the 'N' next to FS.
6. Turn the jog wheel to change the 'N' to 'Y'.
7. Turn the EVAS key back to the upright position.

Author:	Steve Bladon
Approved by:	Rob Trent, Technical Help
Date:	10/07/19

For further help:

Manuals & Guides: technical manuals, installation guides and more are available for download on our website: baldwinboxall.co.uk/downloads.

Telephone: technical help line (0)1892 664422 (then press 3 for after sales technical help).

Training: we hold a range of courses at different levels for engineers. To find out more, or place a booking, please visit our website: baldwinboxall.co.uk/training or contact Carol [@baldwinboxall.co.uk](mailto:carol@baldwinboxall.co.uk).



BALDWIN BOXALL
LEADING THE WAY TO SAFETY

Baldwin Boxall Communications Ltd
Wealden Industrial Estate, Farningham Road,
Crowborough, East Sussex, TN6 2JR, United Kingdom

T: +44 (0) 1892 664422 F: +44 (0) 1892 663146
E: mail@baldwinboxall.co.uk
W: www.baldwinboxall.co.uk